

## **DEPARTMENT OF ENGINEERING**

CAD SEMESTER 2 YEAR 2

## **TUTORIAL 14**



- Create a folder called Lamp Assembly.
- Copy the folders Lamp Base and Lamp Head from

the Q Drive and put these folders into the Lamp Assembly folder. Also copy the spacer part and place it in the Lamp Assembly folder

(These folders contain the parts needed to create the Lamp Assembly)

• Copy the lamp base created in Tutorial 11 and put this in the Lamp Base folder.

(The task is to create a general assembly of the lamp from 2 subassemblies)

- 1 Create a Lamp Base Assembly and save it in the Lamp Base Folder. (Refer to the Lamp Base Assembly dwfx available on the Q drive)
- 2 Create a General Lamp Assembly from the Lamp Base Assembly and the Lamp Head Assembly (Provided)

(Refer to the General Lamp Base Assembly dwfx available on the Q drive)

3 – Save the assembly and also save as Tutorial 14.dwfx for handing in